


AHIMADSTAB

Stéphane COMBET | www.voltige-planeur-rc.net | 29jan2018



Drawn axis-holes are
pre-holes for laser cutting.
Then adjust to 2 and 3mm.